



INSTRUCTOR ADVISORY



Advisory #: 2011 – 06	Date:
Subject: Worthington SP14157 Hydrostatic Requalification	

The purpose of the PSI/PCI Instructor Advisory is to keep PSI/PCI Instructors up to date on the latest information within the industry and to expeditiously disseminate important information

Recently there has developed a situation where Worthington Cylinders SCUBA cylinder SP-14157 have failed hydrostatic requalification. The following information is provided to you for use in counseling those who may be affected by this situation.

When the requalification process has been properly administered (by first conducting the required pretest twice at 89% test pressure followed by the requalification test to test pressure) X-S SCUBA, the distributor of this cylinder, will replace these cylinders when the following information is provided to them:

1. A completed hydrostatic report that shows the requalification process was properly conducted
2. Complete data is recorded from the crown
3. A picture of the cylinder clearly indicating it will not hold gas inclusive of the serial number. X out all markings except serial number and hydro.

For more information you should contact X-S SCUBA customer service at 866.XS.SCUBA (866.977.2822)

Dale Fox
Newsletter Editor